Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO2237Work Order Type: WeatherizationAudit Name: 14014SO2237

CLIENT INFORMATION

Client Name: Address:

Client ID: 14014SO2237 NORMANDY, TN 37360

Alt. Client ID: COFFEE

AGENCY INFORMATION

Agency: SOUTH CENTRAL HUMAN RESOURCE AGENCY Agency Phone: (931) 433-7182

Address: 1437 WINCHESTER HIGHWAY Fax: (931) 438-0074

Company Name & License Number:	
Contractor's Signature:	

<u>COMMENT</u>

Client Name:
Client ID: 14014SO2237
Alt. Client ID: COFFEE

Work Order (Bid Form)

Work Order Name: 14014SO2237 Report Run On: 5/14/2010 DOE Weatherization Assistant

Version 8.5.0 Page 1 of 4

Measures

_	Measure 1 Floo	r Ins. R-19			Componen	<i>t</i> s F1			Inspected
C	Comment								
				Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	960					
2	Labor	Floor Insulation - Fiberglass Batts - R-19	SqFt	960					
C	Other Detail								
L									
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
	Comment INTERIC	ration Redctn			Componen	ts			Inspected
	FLECTE	OR AIR SEAL TO REDU	CE CFM'S	BY 45	•		G AND		
	ELECTF		CE CFM'S	BY 4	•	LUMBING	G AND	Actual	
#			CE CFM'S <i>Unit</i> s	BY 45	50 - SEAL P	LUMBING	G AND Oty		Total
# 1	Material / Labor	RICAL			50 - SEAL P	LUMBING		Actual	
1	Material / Labor Miscellaneous	RICAL Description / Comment	Units	Qty	50 - SEAL P	LUMBING		Actual	
1	Material / Labor Miscellaneous Supplies	Description / Comment Infiltration Reduction	<i>Units</i> Each	Qty	50 - SEAL P	LUMBING		Actual	
1	Material / Labor Miscellaneous Supplies Labor	Description / Comment Infiltration Reduction	<i>Units</i> Each	Qty	50 - SEAL P	LUMBING		Actual	
1	Material / Labor Miscellaneous Supplies Labor	Description / Comment Infiltration Reduction	<i>Units</i> Each	Qty	50 - SEAL P	LUMBING		Actual	
1	Material / Labor Miscellaneous Supplies Labor	Description / Comment Infiltration Reduction	Units Each Hour	Qty 1	50 - SEAL P	LUMBING	Qty	Actual	

Report Run On: 5/14/2010

	Description / Comment Metal Flex	Units		Estimated			Actual	
		Units						
Safety I	Metal Fley		Qty	Unit Cost	Total	Qty	Unit Cost	Total
	IVICIAI FICX	Each	1					
I	Labor	Hour	1					
]	Sub Total:	
			weasur	e Sub Total:		•	Sub Total.	
Press	ureRelief Piping Need	led		•				Inspecte
abor	Description / Comment	Unite	Ofv			Otv		Total
	-	Each	1		TOLAT	Qty	Onit Cost	TOtal
1	Labor	Hour	1					
] [
			Measur	e Sub Total:			Sub Total:	
						1		
:								
1	. <i>abor</i> d Safety	PressureRelief Piping Need abor Description / Comment	PressureRelief Piping Needed Labor Description / Comment Units Safety Pressure relief piping Each Labor Hour	PressureRelief Piping Needed Labor Description / Comment Units Qty Safety Pressure relief piping Each 1 Labor Hour 1	PressureRelief Piping Needed Component Estimated abor Description / Comment Units Qty Unit Cost Safety Pressure relief piping Each 1	PressureRelief Piping Needed Components Estimated Labor Description / Comment Units Qty Unit Cost Total Safety Pressure relief piping Each 1 Labor Hour 1	PressureRelief Piping Needed Components Estimated Labor Description / Comment Units Qty Unit Cost Total Qty Safety Pressure relief piping Each 1	PressureRelief Piping Needed Components Estimated Actual Actual Qty Unit Cost Total Qty Unit Cost Safety Pressure relief piping Each 1 Labor Hour 1

Report Run On: 5/14/2010

DOE Weatherization Assistant Version 8.5.0 Page 3 of 4

-	Measure 5 Smo	ke Detector is Needed			Componen	its			Inspected
C	omment								
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Smoke / Carbon detector	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail								
] []		
					[] []		
				Measur	e Sub Total:		•	Sub Total:	
	-	or Barrier Needed ement/Crawlspace)			Componen	nts			Inspected
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Basement / crawlspace vapor barrier	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail						1		
_				Measur	e Sub Total:		,	Sub Total:	
	Field Notes:								
_			Work Or	der Gra	and Total:		Gran	d Total:	

Report Run On: 5/14/2010